

SERVICE BULLETIN SB Type TRT800_A_H-1/2018 Rev1.00

TO

All operators of f.u.n.k.e. AVIONICS / Funkwerk Avionics / Filser Electronic Mode S transponders.

1 Planning Information

1A Effectivity

Mode-S Transponder TRT800 All Part-Numbers, serial numbers

up to including 30430008

Mode-S Transponder TRT800A All Part-Numbers, serial numbers

up to including 40549908

Mode-S Transponder TRT800H All Part-Numbers, serial numbers

up to including 30480009

All units NOT marked with MOD-Index 11

The "Mod. Index-Label" is attached at the back side of the transponder.

1B Concurrent Requirements

Not applicable

1C Reason

The TRT800H transponder may not be detected by certain interrogator stations in France due to a new interrogation method which is incompatible with the transponder's receiver without modification "MOD 11".

1D Description

In order to avoid disruptions in the affected Mode S air traffic areas, the following Modifications have to be implemented:

Installation of MOD11: Change of receiver board.

1E Compliance

Introduction of this SB is optional.

Service Bulletin

SB-TRT800 A H 1/2018

10.10.2018

Service Bulletin

Formblatt FB-38 Rev4.0 Stand: 05.07.2018



1F Approval

This modification has been approved as minor change to ETSO approvals;

EASA 210.045 (TRT800) EASA.210.268 (TRT800A) EASA.210.269 (TRT800H)

1G Manpower

30 minutes

1H Weight and Balance

Not affected

11 Electrical Load Data

Not affected

1J Software Accomplishment

Not affected

1K Reference

None

1L Publications Affected

Not affected

2 Material Information

Not applicable

3 Accomplishment Instructions

The modification is very comprehensive and can only be done by the manufacturer.

Please send the transceiver to the following address:

f.u.n.k.e. AVIONICS GmbH Heinz-Strachowitz-Str. 4 DE-86807 Buchloe

In order to facilitate a rapid return of shipments in case of repairs, please follow the instructions of the input guide "Reshipment RMA" provided at the Service-Area within the f.u.n.k.e. AVIONICS web portal www.funkeavionics.de

Service Bulletin

SB-TRT800_A_H_1/2018

10.10.2018



3A Working Instructions

Not applicable

- 3B Modification Status Marking Modified transponders will be marked with Modification Index 11.
- 3C Acceptance Testing

After introduction of Modification Index 11 the Mode-S Transponder TRT800 installation checkout shall be done in accordance with the installation and operation Manual TRT800, Document Number 03.2101.010.71, 03.2102.010.71, 03.2103.010.71 to ensure safe aircraft operation.

After introduction of Modification Index 11 the Mode-S Transponder TRT800A installation checkout shall be done in accordance with the installation and operation Manual TRT800A, Document Number 03.2111.010.71, 03.2112.010.71 to ensure safe aircraft operation.

After introduction of Modification Index 11 the Mode-S Transponder TRT800H installation checkout shall be done in accordance with the installation and operation Manual TRT800H, Document Number 03.212.010.71, 03.2122.010.71, 03.2123.010.71 to ensure safe aircraft operation.

4 Release

DO:

70.70.2018 Date

MPL:

QML:

This information has been produced in accordance with alternative procedures to DOA EASA AP013.

Service Bulletin

SB-TRT800_A_H_1/2018

10.10.2018